

April 6, 2018

Version 1

Safety Recall: Front Seats Frame Rivets

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2018	Ridgeline	RT-L, RTL-T, RTL-E, Black Edition	Check the iN VIN status for eligibility.
2018	Pilot	EX, EX-L, Touring, Elite	Check the iN VIN status for eligibility.

BACKGROUND

A limited number of 2018 Pilot and a very limited number of 2018 Ridgeline vehicles were potentially manufactured with defective seat frame rivets in the front seats. If a vehicle with a defective rivet is involved in a crash, the seat may not operate as designed to protect the occupant, leading to increased potential for injury or death. Affected vehicles are on **STOP SALE** until repaired.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

Do not call Tech Line for updates.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.